

Incident Report — INC-2024-010

Vibration Trip | Low Severity

Incident ID	INC-2024-010
Date	2024-06-11
Equipment Tag	500-V-508
Equipment Name	Clarifier
Unit	Effluent Treatment Plant (500)
Type	Vibration Trip
Severity	Low
Investigator	Rajesh Gaikwad (Reliability Engineer, EMP-0013)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2024-06-11, a low severity vibration trip was recorded on 500-V-508 (Clarifier) in the Effluent Treatment Plant. The event was investigated by Rajesh Gaikwad (Reliability Engineer, EMP-0013).

2. Root Cause

Investigation determined the probable root cause to be operator deviation from startup SOP sequence. Contributing factors were reviewed against the governing procedure SOP-500-014 and safety procedure SP-007.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.