

Incident Report — INC-2024-011

Fire Incident | Low Severity

Incident ID	INC-2024-011
Date	2024-04-03
Equipment Tag	400-T-403
Equipment Name	Diesel Storage Tank
Unit	Tank Farm / Storage (400)
Type	Fire Incident
Severity	Low
Investigator	Sunita Patil (Inspection Engineer, EMP-0015)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2024-04-03, a low severity fire incident was recorded on 400-T-403 (Diesel Storage Tank) in the Tank Farm / Storage. The event was investigated by Sunita Patil (Inspection Engineer, EMP-0015).

2. Root Cause

Investigation determined the probable root cause to be inadequate lockout-tagout verification prior to maintenance. Contributing factors were reviewed against the governing procedure SOP-400-010 and safety procedure SP-010.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.