

Incident Report — INC-2025-002

Minor Leak | Medium Severity

Incident ID	INC-2025-002
Date	2025-07-18
Equipment Tag	100-P-101
Equipment Name	Centrifugal Pump
Unit	Crude Distillation Unit (100)
Type	Minor Leak
Severity	Medium
Investigator	Ashok Joshi (HSE Officer, EMP-0035)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2025-07-18, a medium severity minor leak was recorded on 100-P-101 (Centrifugal Pump) in the Crude Distillation Unit. The event was investigated by Ashok Joshi (HSE Officer, EMP-0035).

2. Root Cause

Investigation determined the probable root cause to be mechanical seal wear beyond service life. Contributing factors were reviewed against the governing procedure SOP-100-001 and safety procedure SP-005.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.