

Incident Report — INC-2025-013

Minor Leak | High Severity

Incident ID	INC-2025-013
Date	2025-02-24
Equipment Tag	300-P-305
Equipment Name	Boiler Feed Water Pump
Unit	Utilities & Offsites (300)
Type	Minor Leak
Severity	High
Investigator	Sunil Naik (HSE Officer, EMP-0034)
Regulatory Reportable	Yes
Follow-up Work Order	None issued

1. Incident Summary

On 2025-02-24, a high severity minor leak was recorded on 300-P-305 (Boiler Feed Water Pump) in the Utilities & Offsites. The event was investigated by Sunil Naik (HSE Officer, EMP-0034).

2. Root Cause

Investigation determined the probable root cause to be operator deviation from startup SOP sequence. Contributing factors were reviewed against the governing procedure SOP-300-009 and safety procedure SP-007.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. Given the severity and regulatory relevance of this event, a formal submission was filed with the applicable regulatory authority.