

Inspection Report — 200-PSV-207

Vibration Analysis | 2026-01-17

Report ID	IR-200-PSV-207-2026-022
Equipment Tag	200-PSV-207
Equipment Name	Reactor Relief Valve
Unit	Hydrocracker Unit (200)
Inspection Date	2026-01-17
Inspection Type	Vibration Analysis
Inspector	Shalini Naik (Inspection Engineer, EMP-0014)
Next Due Date	2027-01-17
Governing SOP	SOP-200-006

1. Scope

Risk-Based Inspection (RBI) assessment of 200-PSV-207 performed by Shalini Naik (Inspection Engineer, EMP-0014) in accordance with SOP-200-006 and OISD inspection guidelines.

2. Findings

Vibration Analysis inspection of 200-PSV-207 (Reactor Relief Valve) on 2026-01-17 found the equipment in satisfactory condition with no reportable defects. Readings are within acceptable limits per design basis.

3. Recommendation

Continue on standard RBI interval. Next inspection due 2027-01-17.