

Inspection Report — 300-P-309

Ultrasonic Thickness | 2025-06-22

Report ID	IR-300-P-309-2025-024
Equipment Tag	300-P-309
Equipment Name	Firewater Pump
Unit	Utilities & Offsites (300)
Inspection Date	2025-06-22
Inspection Type	Ultrasonic Thickness
Inspector	Sunita Patil (Inspection Engineer, EMP-0015)
Next Due Date	2025-12-19
Governing SOP	SOP-300-009

1. Scope

Risk-Based Inspection (RBI) assessment of 300-P-309 performed by Sunita Patil (Inspection Engineer, EMP-0015) in accordance with SOP-300-009 and OISD inspection guidelines.

2. Findings

Ultrasonic Thickness inspection of 300-P-309 (Firewater Pump) on 2025-06-22 found the equipment in satisfactory condition with no reportable defects. Readings are within acceptable limits per design basis.

3. Recommendation

Continue on standard RBI interval. Next inspection due 2025-12-19.