

Maintenance Work Order — WO-2024-0036

Predictive | 300-TUR-302

Work Order ID	WO-2024-0036
Date	2024-08-07
Equipment Tag	300-TUR-302
Equipment Name	Steam Turbine Generator
Unit	Utilities & Offsites (300)
Type	Predictive
Assigned To	Tanvir Shaikh (Maintenance Engineer, EMP-0009)
Downtime (hrs)	9.8
Cost (INR)	586,128
Status	In Progress
Linked Incident	None

1. Job Description

Predictive maintenance job on 300-TUR-302 (Steam Turbine Generator): vibration analysis triggered bearing replacement. Work performed by Tanvir Shaikh (Maintenance Engineer, EMP-0009).

2. Safety & Isolation

Work executed under isolation per SP-008 (Chemical Handling and Spill Response - ETP). Governing operating procedure: SOP-300-008.

3. Outcome

Equipment downtime of 9.8 hours recorded. Total job cost INR 586,128. Work order status: In Progress.