

LD=1 PF=1 LP=10 RM=74

Workstation (Mike Grubbs)

"It's not trying to be a full-purpose, full-feature package."

"It's purpose is to introduce the user to word processing, spreadsheets, file management, so when he goes out for a full-fledged system he'll know what he's looking for."

"It provides a set of tools he can use immediately and also educate himself about the machine."

"generic software package." "generic function set"

also, a tool to be used in sales

Software (D. Frager)

won't use express Order software very much

"I'm not going to send people directly to another retailer"

"Yes, I'm going to tell them they can buy software elsewhere but I'm not going to recommend it."

"This is a PC plus enhancements."

more color and higher res graphics. It has all the things that are optional in the standard unit.

"Our list of features is as long as their option list."

"We want people to know that we are better."

"For the small businessman who needs to run the basic applications the 4 or 4P will be plenty. For someone who is running special applications where MS-DOS might be important or someone who needs expansion capabilities or someone who needs color then the machine is the Model 1000."

"The Model 1 is not a dead product. For the price the Model 4 is a strong contender for the small business market."

LS=1 PF=1 LM=10 RM=74

Compatibility

From Software Developer's Guide:

1. Keyboard--scan codes at hardware interrupt level differ; "software that accesses the keyboard ports directly will not function properly." games in particular
2. Timing--"Any software that uses software timing or delay loops will not function as on the PC....In general such software will not run without modification and, in fact, must be configured for memory size."
3. Monochrome memory board--"...software written to run on the monochrome adapter will not function properly."
4. Memory--Video graphics memory (16 or 32K) subtracted from user RAM. GW Basic RAM resident, reduces RAM available for program storage by about 25K less than that available to a Basic application on PC. Applications that require nearly all of a 128K PC and most Basic applications will require 256K.
5. DMA support only with second 128K; applications that require that disk I/O be DMA driven will require 256K.
6. Does not support configuration switches.
7. Joystick software probably will not work.
8. Printers--96 printable ASCII characters same as on Epson. Special characters, codes, backspace, graphics "cannot be expected to work." CR=CR & LF; IBM generates "explicit LFs."
9. Port addresses--"If software uses port addresses as documented in the IBM PC Technical Reference Manual, there will be no problem."
10. FDC--"Software that directly accesses the floppy disk controller probably will not work unless the DMA facility is present and even then this software might fail."
11. NMI--"enabling and disabling the nonmaskable interrupts will probably conflict with the mapping of video RAM. Software that accesses the NMI port A0 probably will not run....The standard PC does not use NMI."
12. BIOS routines--"The functions and vectors will be identical but internal service routines will differ in location and code. The name and location of publicly used data areas will be published....In general using BIOS data areas is an area of concern."