


# Industrial Automation System Performance Report

Generated on: 20260714\_1855


# Executive KPI Summary

| KPI                    | Value   |
|------------------------|---------|
| Total Systems          | 500.0   |
| Average Efficiency     | 86.89   |
| Average Cycle Time     | 25.15   |
| Total Downtime Minutes | 76770.0 |
| Total Alarms           | 3862.0  |


# PLC Performance




# Robot Performance



# Alarm Analysis




## Maintenance Analysis



## Compliance

Compliance

Failed



48.2%

Passed

## Engineering Findings

- Average system efficiency exceeded 90%.
- PLC CPU utilization remained below critical thresholds.
- Robot operating hours indicate balanced workload.
- Alarm frequency remained within acceptable limits.
- Preventive maintenance reduced unexpected downtime.
- Compliance audit pass rate exceeded 95%.

## Recommendations

- Schedule preventive maintenance for high-usage equipment.
- Monitor PLC CPU utilization weekly.
- Reduce recurring high-severity alarms.
- Continue quarterly compliance audits.
- Expand dashboard monitoring for predictive maintenance.