

PLASMA SPRAY PROCESSORS Works Instruction	QF/QMS/02/01	
	Rev. 01	
	Date : 12/02/2024	

Operations/Work/Job Activity covered by this assessment: Inward					
Scope: To receive the components/material from the customer with appropriate Quantity, Delivery Challans /PO's.					
Work Instructions: 1. Check Delivery Challan for Part Description & Qty , Incase Shortfall inform/email Customer. 2. Check if Delivery Challan is not received with job, inform/email Customer. 3. Open CRM Software with your log in ID. 4. Check quotation list and select the appropriate quote look for Customer's Name and Part Description and select the Sales Order Cell and clinched with Quote, enter Challan No & Date, Po No & Date, Select Qty Cell and enter the exact qty, enter Price/ Rate, and Delivery Date as committed and SAVE the Sales Order. 5. A unique Sales Order is created. 6. Recheck the description, qty, price, tax etc.. and terms and condition mention in the PO. Any discrepancies found inform the Customer/WM for approval & Keep signed PO by Inbound Sales representatives (ISR). 7. Select Pre Inspection Report cell and take a print of Pre-Inspection Report. A unique ID is created for Pre-Inspection Report. 8. All the relevant supporting documents & records to be filed and stored at office Cupboard No. 3 & 4.					
Assessor :		Signature:		Date:	
Approved:		Signature:		Date:	