

PLASMA SPRAY PROCESSORS	QF/QMS/02/11	
	Rev. 00	
	Date : 01/03/2019	
Works Instruction		

Operations/Work/Job Activity covered by this assessment: Outward					
Scope: To send the component to the customer with appropriate Quantity, Delivery Challan/Invoices.					
Works Instructions: 1. Check the status “Ready for Dispatch” in the IN-OUT sheet maintained. 2. Check the Yellow tags are tagged on the components duly Stamp “Inspected” on it. 3. Check for proper packing and the wooden box properly labeled. 4. Check the concerned job card and make sure all relevant documents are attached (PIR, Drg & FIR) 5. Select the relevant SO from CRM software, prepare DC by clinching the DC Key on the screen. 6. Fill the Quantity, save it and print 2 Copies of DC (1-party & 1-office use). 7. Clinch Tax Invoice from DC and enter taxes as per SO, print 3 copies of TI (2-party, 1-office). 8. On request, send FIR and test certificates required by the customer. 9. Inform the customer about the dispatch details i.e. transporter/Courier Agency, Scan LR/ Docket copy and mail/telephone them to the customer. 10. Enter dispatch detail in the IN-Out Sheet along with material LR/Docket No. 11. All the relevant supporting documents & records to be filed and stored.					
Assessor :	Prasanna Wadkar	Signature:	PSW	Date:	03.01.2019
Approved:	Haarsh Doshi	Signature:	HDD	Date:	03.01.2019