

**Works Instruction**

Operations/Work/Job Activity covered by this assessment: Cleaning Of components

Required Personal Protective Equipment (PPE) :**Safety glasses must be worn at times.****Long and loose hair must be contained.****Appropriate footwear with substantial uppers must be worn.****Close fitting/protective clothing to cover arms and legs must be worn.****Respiratory protection devices required.****Oil free leather gloves and spats must be worn.****Hearing protection must be used when using this machine.****Operations Procedure:**

1. Purpose of Cleaning is to ensure a clean and defect free surface. To proceed with the coating process.
2. Ensure that work area is clean and clear of grease, oil and any flammable materials.
3. Remove excess grease/oil by means cotton rags soaked in kerosene and wipe the component thoroughly.
4. Use only Acetone for aviation components which are made of Titanium and other parts with Trichloroethylene or as per instruction given by the Supervisor/ Works Manager.
5. Wipe the component thoroughly and rigorously.
6. For smaller components immerse them in the container with respected solution.
7. In case excess oil is found on the component's coating surface use a burner to heat and remove the excess oil.
8. In case any burr, sharp edges or rusting is observed on the component use emery paper or pneumatic tools to remove deformities to ensure a smooth and a clean surface.

Assessor :

Signature:

Date:

Approved:

Signature:

Date: