

PLASMA SPRAY PROCESSORS Works Instruction	QF/QMS/02/16	
	Rev. 01	
	Date : 26/02/2023	

Operations/Work/Job Activity covered by this assessment: Inward of Raw Material					
Scope: To receive the material from our Vendors with appropriate Quantity, Test Certificates, MSDS, Delivery Challans, Invoice.					
Work Instructions: 1. Check Part Description, Qty w.r.t. Vendor's Challan. Check for proper Packaging of the parts, if found damaged, take a photograph and inform/email Vendor. 2. Open CRM Software with your log in ID. 3. Check PO and match the exact qty, Price/ Rate, and Terms as committed. Any discrepancies found, inform the Vendor. 4. Collect Test Certificates, MSDS, Certificates, Service Report and Inspection Report etc... from respective Vendors. 5. Review and acknowledge the Test Certificates for Powder and <i>Blasting media</i> as per the Vendor Technical Specs. 6. Enter the same in Supplier Material Inward File. 7. Store the material in the respective compartments and Tag. 8. All relevant documents & records to be filed and stored.					
Assessor :		Signature:		Date:	
Approved:		Signature:		Date:	