PLASMA SPRAY PROCESSORS Works Instruction	QF/QMS/02/26 Rev. 00 Date : 12-03-23	PLASMA SPRAY PROCESSORS

Operations/Work/Job Activity covered by this assessment: Visual Inspection

Required Personal Protective Equipment (PPE) :



Safety glasses must be worn at times.



Long and loose hair must be contained.



Appropriate footwear with substantial uppers must be worn.



Close fitting/protective clothing to cover arms and legs must be worn.



Respiratory protection devices required.



Oil free leather gloves and spats must be worn.



Hearing protection must be used when using this machine.

Loading & Unloading Check:

1. Ensure no slip/trip is present in work pass and walk ways.
2. Ensure that work area is clean and clear of grease, oil and any flammable materials.
3. Refer Work Instructions PSP/WI/14 while handling.

Operations Procedure:

Visual inspection qualification: -

1. Only those personnel, Certified NDT level II or higher is qualified.
2. It shall perform when access is sufficient to place the eye within 24" of the surface and angle not less than 30° to the surface to be examined
3. Minimum light level shall be at least 750 to 1000 lux.
4. Artificial light can be used such as flashlight, drop light or ant other similar form of light to maintained minimum light level.
5. Magnifying lens can be used.

Scope: To check whether the coating and finished product as per customer requirements.

1. Take out print of FIR (Final-Inspection Report) format from software.
2. FIR indicates the Customer Name, Part Name, Qty etc…
3. Carry out Visual Inspection to check scratch, dents, pinholes, coating discontinuities etc.,
4. Compare the component with Pre-inspection Report/ Drawing given by the Customer.
5. Record components details like, punch no and mention any remark/observation in the remark cells.
6. If discontinuities are found contact your Production Engineer/ Works Manager, and get clearance from the them
7. After getting the approval from the Production Engineer/ Works Manager, perform final inspection procedure.

Assessor :		Signature:		Date:	
Approved:		Signature:		Date:	