Polywatch (Sleep Study) Patient Guide

1. Button Function

On-Off/OK Button: Turn on/off the device, confirm adjustment.

Shift Button: Switch interfaces and options.

If there is no “Exit” on menu page, press and hold these two buttons together to exit menu page.

2. Setting up the Device

(1) Wear main device on the wrist (preferentially on left wrist) like a watch, and fasten the wrist belt and move the main device to a comfortable position.



(2) Wear and fasten the respiration effort belt around the body. Insert the effort lead cable into the holes on the respiration kit, and hang the respiration kit on the respiration effort belt.



(3) Make the two small open tubes on airflow cannula point towards your nostrils. Fit the loop around your ears and then back around your neck, without pulling over your head. Draw the cannula to a comfortable position under your chin, place adhesive tape as indicated to help secure the cannula.



(4) Fit the airflow cannula to the connections of the respiration kit by turning it clockwise, then insert the data connector of the respiration kit into the **Flow/COM port** on the right side of the device.



(5) Insert the index finger into the pulse oximeter sensor. The finger must reach the end of the sensor, but don't over the end of the sensor. Insert the data connector of the pulse oximeter sensor into the **SpO_2 port** on the top of the main device.



(6) The figure below shows what it looks like when each accessory is fitted.

For support, contact our friendly team on

020 7381 8698 or admin@ipdiagnostics.co.uk

iPD IAGNOSTICS

3. Recording

(1) Power on device by pressing and holding **On-Off/OK Button** ⏻/✓ for approximately five seconds, enter the "Record" interface.  	(2) If each accessory is connected well, the "Record" interface can be accessed. The time notification (0:00:00) in the upper left corner of the "Record" interface flickers. Press and hold the **On-Off/OK Button** for approximately two seconds to start recording. 
(3) Stop the recording by pressing and holding the **On-Off/OK Button** and **Shift Button** ⏻/✓ + ⟲ simultaneously approximately three seconds. Power off device by pressing and holding **On-Off/OK Button** ⏻/✓ for approximately five seconds.	