- 2. Kupfer unten
- 3. Kuper Oben
- 4. componentmask
- 5. soldermask
- 6. plated-drill
- 7. unplated-drill
- 8. topsilk
- 9. bottomsilk
- 10. topassembly
- 11. bottomassembly
- 12. fab





















