

Source	Document	Page	Evidence excerpt	Review status
S1	demo-sop.txt		1 FICTIONAL SOP DEMO-01 revision 1 Damaged equipment identification labels require review by the maintenance supervisor. Costs must be supplied separately before financial approval. This is demonstration material, not an MRPL procedure.	Needs human review
S2	inspection-scan.pdf		1 FICTIONAL DEMONSTRATION REPORT Inspection reference: DEMO-002 Equipment: P-101 Finding: identification label damaged, Recommendation: replace the damaged label after review. Cost: not provided. No operational safety conclusion is supplied.	Needs human review

Draft for review

Please review the following source observations before deciding any action.

[S1] FICTIONAL SOP DEMO-01 revision 1

Damaged equipment identification labels require review by the maintenance supervisor. Costs must be supplied separately before financial approval. This is demonstration material, not an MRPL procedure.

[S2] FICTIONAL DEMONSTRATION REPORT

Inspection reference: DEMO-002

Equipment: P-101

Finding: identification label damaged,

Recommendation: replace the damaged label after review.

Cost: not provided.

No operational safety conclusion is supplied.

Costs and authorization details require reviewer confirmation.