Sr.No. Hex Code	Command to LCD instruction Register
1 01	Clear display screen
2 02	Return home
3 04	Decrement cursor (shift cursor to left)
4 06	Increment cursor (shift cursor to right)
5 05	Shift display right
6 07	Shift display left
7 08	Display off, cursor off
8 0A	Display off, cursor on
9 OC	Display on, cursor off
10 OE	Display on, cursor blinking
11 OF	Display on, cursor blinking
12 10	Shift cursor position to left
13 14	Shift the cursor position to the right
14 18	Shift the entire display to the left
15 1C	Shift the entire display to the right
16 80	Force cursor to the beginning (1st line)
17 CO	Force cursor to the beginning (2nd line)
18 38	2 lines and 5×7 matrix