

Northgate Accident Repair Centre

Unit 14 Northgate Industrial Estate, Coventry CV6 5RU
Tel 024 7655 0142 · VAT Reg GB 482 5571 09

INVOICE

No. NRC-24881
Date: 2026-05-12

Claim reference	CLM-A	Insurer	Allianz Insurance plc
Vehicle	2021 Volkswagen Golf 1.5 TSI Life (Silver)	Registration	LP21 ZRT
VIN	WVWZZZ1KZMW402188	Mileage	31,420
Labour rate	£55.00 / hour	Payment terms	30 days net

Description	Qty / Hours	Unit	Amount
PARTS			
Front bumper cover - aftermarket (OE-equivalent)	1 ea	£210.00	£210.00
Offside (driver) headlamp unit - aftermarket	1 ea	£180.00	£180.00
Clips, fixings & consumables	1 ea	£25.00	£25.00
LABOUR			
Remove & refit front bumper, O/S corner	1.5 hrs	£55.00	£82.50
Replace & align O/S headlamp	0.8 hrs	£55.00	£44.00
PAINT			
Refinish front bumper (prep, prime, colour)	2 hrs	£55.00	£110.00
Paint materials & sundries	1 ea	£85.00	£85.00
Subtotal (ex VAT)			£736.50
VAT @ 20%			£147.30
Total due			£883.80

Repairer notes: Light front O/S impact. Repairs limited to front bumper corner and driver-side headlamp.
This estimate is submitted for insurer authorisation prior to commencement of repair work.