


MCU Connections




Categorized Designs




Crystal Oscillator



Test Points, LEDs



CAN Transceiver





Purdue ROV

Sheet: /
File: X19-Control-Board.kicad_sch

Title: Purdue ROV Subsystem Board

Size: A4	Date:	**Rev:**
KiCad E.D.A. 10.0.5-unknown		Id: 1/5


SOL_PWR
D5
1N5819HW-7-F
R15
220
SOL1A
SOL1A-
Q1
Q_NMOS_GSD
R11
10k
SOL1A-
SOL1B-
J2
SM02B-GHS-TB
D9
R23
SOL3A
SOL3A-
Q5
R19
SOL3A-
SOL3B-
J3
D13
R29
SOL5A
SOL5A-
Q9
R27
SOL5A-
SOL5B-
J6
D6
R16
SOL1B
SOL1B-
Q2
R12
D10
R24
SOL3B
SOL3B-
Q6
R20
D14
R30
SOL5B
SOL5B-
Q10
R28
D7
R17
SOL2A
SOL2A-
Q3
R13
SOL2A-
SOL2B-
J1
D11
R25
SOL4A
SOL4A-
Q7
R21
SOL4A-
SOL4B-
J4
12V
J5
SM06B-GHS-TB
D8
R18
SOL2B
SOL2B-
Q4
R14
D12
R26
SOL4B
SOL4B-
Q8
R22
Sheet: /MOSFET_driver/
File: untitled.kicad_sch
Title:
Size: A4
Date:
Rev:
KiCad E.D.A. 10.0.5-unknown
Id: 2/5




Sheet: /Sensors_Telemetry/
File: Sensors_Telemetry.kicad_sch


Title:

Size: A4	Date:	**Rev:**
KiCad E.D.A. 10.0.5-unknown		Id: 5/5

Power Monitoring 5.2V, 12V rails



LDO – Voltage Conversion




Sheet: /Voltage Conv-Protec-Monitoring/
File: Voltage_conv_prot.kicad_sch


Title:

Size: A4	Date:	**Rev:**
KiCad E.D.A. 10.0.5-unknown		Id: 6/5


THIS PINOUT IS NOT FINAL



Break Out SWD



Break Out Communication



Place close to MCU

Connector added for debug if there is space

Sheet: /Connector_Signals/		
File: connector_signals.kicad_sch		
Title:		
Size: A4	Date:	**Rev:**
KiCad E.D.A. 10.0.5-unknown		Id: 7/5