





Purdue ROV

Sheet: /
File: X19-Control-Board.kicad_sch

Title: Purdue ROV Subsystem Board

Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.5-unknown		Id: 1/6



Sheet: /MOSFET_driver/
File: untitled.kicad_sch

Title:


Size: A4


Date:



KiCad E.D.A. 10.0.5-unknown

Rev:

Id: 2/6







Sheet: /Voltage Conv-Protec/
File: Voltage_conv_prot.kicad_sch

Title:


Size: A4

Date:

KiCad E.D.A. 10.0.5-unknown

Rev:

Id: 6/6



Break Out SWD

nRST

1

2

SWCLK

3

SWDIO

4

3.3V

5

J6

Conn_01x05

I'm down to add a bigger ST-Link one, but we need to know v2, v3, etc

J8

Mega Connector/Breakout (if we have space)

nRST

1

GATE1

2

GATE2

3

GATE3

4

GATE4

5

MOSI

6

SCLK

7

MISO

8

GATE5

9

GATE6

10

GATE7

11

GATE8

12

GATE9

13

GATE10

14

STM_TO_INPUT_CAN

15

STM_TO_OUTPUT_CAN

16

32

31

30

29

28

27

26

25

24

23

22

21

20

19

18

17

PWM_A1

PWM_A2

PWM_B1

PWM_B2

PWM_C1

PWM_C2

PWM_D1

PWM_D2

SWCLK

SWDIO

SDA

SCL

CS_BMI

nINT_BN0

RST_BN0

INT1_BMI

NOT USED

USB C 2.0 (Want to do it, but is useless here)

P1

USB_C_Plug_USB2.0

VBUS

A4

CC

A5

VCONN

B5

D-

A7

D+

A6

SHIELD

A1

GND

5.2V

Sheet: /Connector_Signals/
File: connector_signals.kicad_sch

Title:

Size: A4

KiCad E.D.A. 10.0.5-unknown

Date:

Rev:

Id: 7/6