
▲ Touch Panel Sensor Test

01. Open the file to find the right document .


GalaxWorks80H84~20180929-YLHD-21.5_3mm-0693-v00_T1

名称	修改日期	类型	大小
eGalaxUpdateLog	2019.08.27 上午 10:12	文件夹	
Log_0693	2019.08.27 上午 9:35	文件夹	
eGalax.dat	2018.08.01 下午 2:05	DAT 文件	2 KB
eGalax5960Suite.exe	2018.09.29 下午 2:56	应用程序	2,028 KB
eGalaxBuilder5.exe	2018.09.29 下午 2:56	应用程序	3,226 KB
eGalaxCalibration.exe	2018.09.29 下午 2:56	应用程序	3,108 KB
🗟 eGalaxCalibration.ini	2018.09.29 下午 2:56	配置设置	1 KB
eGalaxFPCTester.exe	2018.09.29 下午 2:56	应用程序	2,068 KB
eGalaxFPCTester.ini	2018.09.29 下午 2:56	配置设置	1 KB
eGalaxSensorTester4.exe	2018.09.29 下午 2:56	应用程序	2,408 KB
eGalaxTestAnalyzer.exe	2018.09.29 下午 2:56	应用程序	2,170 KB
≅ eGalaxTuner_80HXXX.exe	2018.09.29 下午 2:56	应用程序	2,769 KB
🗟 eGalaxUpdate.ini	2018.89.29 下午 2:56	配置设置	3 KB
👪 eGalaxUpdate2.exe	2018.11.27 上午 11:18	应用程序	4,050 KB
m EULA.pdf	2018.09.29 下午 2:56	看图王 PDF 文件	192 KB
MIDdapi.dll	2018.09.29 下午 2:56	应用程序扩展	2,075 KB
LastTestLog.txt	2019.08.27 上午 10:13	文本文档	1 KB
OPDraw.exe	2018.09.29 下午 2:56	应用程序	2,562 KB
OPDraw.ini	2018.09.29 下午 2:56	配置设置	9 KB
PCAP80H84_0693_v00_T1_00	2018.09.29 下午 2:56	H84 文件	199 KB
SensorTest_Result.txt	2019.08.27 上午 10:13	文本文档	1 KB
SensorTestDefault.ini	2018.09.29 下午 2:56	配置设置	4 KB
UniformityTableResult.txt	2019.08.27 上午 10:13	文本文档	1 KB


02. Click Start Test




03. Wait the test to be done, No operation needed during this process



04. Sensor Test Result



If It shows "Pass " it means the touch panel functionally OK If shows "Fail", it means test is failed, Please send us the testing log for analysis.





Update Firmware


01. Connect USB cable to Computer, Then open the testing file


名称	修改日期	类型	大小
- eGalaxUpdateLog	2019.09.17 下午 3:19	文件夹	
Log_0693	2019.08.27 上午 9:35	文件夹	
eGalax.dat	2018.08.01 下午 2:05	DAT 文件	2 KB
eGalax5960Suite.exe	2018.09.29 下午 2:56	应用程序	2,028 KB
eGalaxBuilder5.exe	2018.09.29 下午 2:56	应用程序	3,226 KB
eGalaxCalibration.exe	2018.09.29 下午 2:56	应用程序	3,108 KB
aGalaxCalibration.ini	2018.09.29 下午 2:56	配置设置	1 KB
eGalaxFPCTester.exe	2018.09.29 下午 2:56	应用程序	2,068 KB
eGalaxFPCTester.ini	2018.09.29 下午 2:56	配置设置	1 KB
eGalaxSensorTester4.exe	2018.09.29 下午 2:56	应用程序	2,408 KB
eGalaxTestAnalyzer.exe	2018.09.29 下午 2:56	应用程序	2,170 KB
eGalaxTuner_80HXXX.exe	2018.09.29 下午 2:56	应用程序	2,769 KB
eGalaxUpdate.ini	2018.09.29 下午 2:56	配置设置	3 KB
👪 eGalaxUpdate2.exe	2018.11.27 上午 11:18	应用程序	4,050 KB
EULA.pdf	2018.09.29 下午 2:56	看图王 PDF 文件	192 KB
MIDdAPI.dll	2018.09.29 下午 2:56	应用程序扩展	2,075 KB
LastTestLog.txt	2019.09.17 下午 3:20	文本文档	1 KB
₩ OPDraw.exe	2018.09.29 下午 2:56	应用程序	2,562 KB
OPDraw.ini	2018.09.29 下午 2:56	配置设置	9 KB
PCAP80H84_0693_v00_T1_00	2018.09.29 下午 2:56	H84 文件	199 KB
SensorTest_Result.txt	2019.09.17 下午 3:20	文本文档	1 KB
SensorTestDefault.ini	2018.09.29 下午 2:56	配置设置	4 KB
UniformityTableResult.txt	2019.09.17 下午 3:19	文本文档	1 KB
<u></u>	- -		


02. Click "load image" to load the latest firmware .












Change The Touch Direction (Only For 31XX Series)

01. Open the file



02 .Reset the touch direction as below and click "Save"

