
Time to Load a Railcar by Commodity



Average Load Times: Bush = 21:11, HMS = 10:12, P&S = 13:32, RCS = 30:59, Shred = 15:14