


Rough Milling • Sharp LMV CNC Mill 3.0 hp, 50% load • 2" 1 fl. HSS/Cobalt End Mill




Rough Milling • Sharp LMV CNC Mill 3.0 hp, 50% load • 3/4" 4 fl. HSS/Cobalt End Mill




Rough Milling • Sharp LMV CNC Mill 3.0 hp, 50% load • 5/8" 4 fl. HSS/Cobalt End Mill




Rough Milling • Sharp LMV CNC Mill 3.0 hp, 50% load • 1/2" 4 fl. HSS/Cobalt End Mill




Rough Milling • Sharp LMV CNC Mill 3.0 hp, 50% load • 1/2" 4 fl. Carbide End Mill




Rough Milling • Sharp LMV CNC Mill 3.0 hp, 50% load • 3/8" 4 fl. Carbide End Mill



Rough Milling • Sharp LMV CNC Mill 3.0 hp, 50% load • 3/8" 2 fl. HSS/Cobalt End Mill



Rough Milling • Sharp LMV CNC Mill 3.0 hp, 50% load • 3/8" 2 fl. Carbide End Mill



Rough Milling • Sharp LMV CNC Mill 3.0 hp, 50% load • 3/16" 2 fl. Carbide End Mill

