

Single Mosfet JH, HA and Absolute Junction Temperature
T_{jh}
T_{ha}
T_j
T/K
100
50
0
1
2
3
4
5
6
Single Mosfet Power Losses
P_{loss}
P/W
15
10
5
0
1
2
3
4
5
6
t/s