

Single Mosfet JH, HA and Absolute Junction Temperature
100
50
0
T/K
1
2
3
4
5
6
T_{jh}
T_{ha}
T_j
Single Mosfet Power Losses
20
15
10
5
0
P/W
1
2
3
4
5
6
t/s
P_{loss}