

Single Mosfet JH, HA and Absolute Junction Temperature
100
50
0
T/K
T_{jh}
T_{ha}
T_j
1
2
3
4
5
6
Single Mosfet Power Losses
15
10
5
0
P/W
P_{loss}
1
2
3
4
5
6
t/s