

MV AC 3phase system

$$\vec{u}_g^{\,ac}(t)=\begin{bmatrix}u_u(t) & u_v(t) & u_w(t)\end{bmatrix}^T$$

$$\vec{i}_g^{\,ac}(t)=\begin{bmatrix}i_u(t) & i_v(t) & i_w(t)\end{bmatrix}^T$$





each master module has the following information

$$\hat{\vartheta}_{pll}(t),\quad \vec{u}_{\xi\eta}^{\,p}(t),\quad \vec{u}_{\xi\eta}^{\,n}(t)\quad \vec{i}_{\xi\eta}^{\,p}(t),\quad \vec{i}_{\xi\eta}^{\,n}(t),\quad u_g^{dc}(t)$$

