
Phase u over one period at the operating point (|u| = 0.913 pu, delta = 4.3 deg)
[pu]
1.0
0.5
0.0
−0.5
−1.0
0
45
90
135
180
225
270
315
360
angle of the converter current of phase u [deg]
pole reference and current of opposite sign
pole reference, zero sequence on the current sign
pole reference, min-max zero sequence
converter current [pu]