D	0	Task	Task Name	Duration	Start	Finish	Predecessors	Resource Names	12		L, 2013	Qtr 2, 20	
1		Mode	Complete Gantt Chart	2 days	Sat 1/12/13	Sun 1/13/13		+	Dec	Jan	rep Mar	r Apr Ma	y  Jur 
2	1	AT.	· ·							†			
	1					Sat 2/23/13	2						
3		<b>☆</b>	-	3 days									
4		7	•	5 days	Wed 2/27/13		3					'a	
5		A.		0 days		Sun 3/3/13					<b>♦ 3/</b>	13	
6		A <sup>*</sup>	Hydroponic System Integration	7 days	Fri 2/8/13	Thu 2/14/13							
7		*	Reservior Integration	2 days	Sat 2/9/13	Sun 2/10/13				.	I		
8		A <sup>®</sup>	Water Table Integration	3 days	Sun 2/10/13	Wed 2/13/13	7				1.		
9		₹	pH Sensor	19.75 days	Sat 2/16/13	Thu 3/7/13							
10		*	pH Sensor Design	10.75 days	Sat 2/16/13	Tue 2/26/13							
11		*	PH Sensor Prototype	3 days	Tue 2/26/13	Fri 3/1/13	10						
12		*	pH Sensor Integration	6 days	Fri 3/1/13	Thu 3/7/13	11						
13		*	Laser System	14 days	Mon 2/11/13	Sun 2/24/13							
14		*	Laser System Design	7 days	Mon 2/11/13	Sun 2/17/13					t)		
15		A.	Laser System Prototype	- '	Mon 2/18/13								
16		*	Laser System Integration	2 days	Thu 2/21/13	Fri 2/22/13	15				<b>*</b>		
17		₹ <sup>®</sup>		20.75 days	Sun 1/20/13	Sat 2/9/13					<b>\</b>		
18		A P		•		Wed 1/23/13				L			
19		A <sup>*</sup>		5 days		Tue 1/29/13				I	•		
20		*		4 days	Sat 3/2/13	Tue 3/5/13							

	Task		External Milestone	<b>♦</b>	Manual Summary Rollup	
	Split		Inactive Task		Manual Summary	<b>-</b>
Project: SDP Gantt Chart	Milestone	<b>•</b>	Inactive Milestone	$\Diamond$	Start-only	С
Date: Thu 2/14/13	Summary	<del>-</del>	Inactive Summary		Finish-only	3
	Project Summary	$\overline{}$	Manual Task		Deadline	<b>₽</b>
	External Tasks		Duration-only		Progress	

D	0	Task Mode	Task Name		Duration	Start	Finish	Predecessors	Resource Nam		Qtr 1, 2013 Jan Feb Ma	Qtr 2, 201	
21		A	Temperatur Prototype	e Sensor	1 day	Sat 3/2/13	Sat 3/2/13				<b>I</b>		
22		*	Humidity Co Integration	ontrol	2 days	Sun 3/3/13	Mon 3/4/13				I		
23		*	Humidity Co Prototype	ontrol	1 day?	Sat 3/2/13	Sat 3/2/13				I		
24		₹*	Temperatur Integration	e Sensor	2 days	Sun 3/3/13	Mon 3/4/13				I		
25		*	<b>Nutrient Sensi</b>	ng	6 days	Fri 3/8/13	Wed 3/13/13				•		
26		*	TDS Sensor	Prototype	2 days	Fri 3/8/13	Sat 3/9/13				I		
27		*	TDS Sensor	Integration	2.25 days	Sat 3/9/13	Sun 3/10/13				Ţ		
28		*	All Sensors I	ntegrated	0 days	Sun 3/10/13	Sun 3/10/13				<b>♦</b>	3/10	
29		*	Pumps & Irriga	ation	8 days	Thu 2/21/13	Thu 2/28/13						
30		*	Air Pump In	tegration	1 day	Fri 2/22/13	Sat 2/23/13				I		
31		A <sup>*</sup>	Water Pump Impementa		2 days	Thu 2/21/13	Fri 2/22/13				I		
32		*	Irrigation Sy Implementa		3 days	Fri 2/22/13	Mon 2/25/13						
33		A <sup>P</sup>	Water Filter	Integration	2 days	Thu 2/21/13	Fri 2/22/13				I		
34		*	Lighting		14 days	Tue 3/5/13	Mon 3/18/13					ı	
35		*	Ballast Desig	gn	7 days	Tue 3/5/13	Mon 3/11/13						
36		*	Ballast Integ	gration	3 days	Thu 3/14/13	Sat 3/16/13				I		
37		A <sup>*</sup>	Lighting Cor	ntrol Design	3 days	Fri 3/8/13	Sun 3/10/13				I		
			Tasi	k			External Mileston	ne 🔷	М	anual Summ	nary Rollup 🕳		
			Spli	t			Inactive Task			anual Summ			
Project: SDP Gantt Chart Milestone			<b>•</b>		Inactive Milestor	ne �		art-only			•		
Date:				nmary	nmary		Inactive Summar			nish-only	_		
				, ject Summary			Manual Task			Deadline ♣			
			Exte	ernal Tasks			Duration-only		Pr	ogress			

Page 2

)		Task		Duration	Start	Finish	Predecessors	Resource Names	12	Qtr 1,		Qtr 2, 20	
	0	Mode							Dec	Jan F	eb Mar	Apr May	∕∐Ju
38		A <sup>P</sup>	Lighting Control Integration	4 days	Thu 3/14/13	Sun 3/17/13					1		
39		A .	Fans & Exhaust	5 days	Fri 3/15/13	Tue 3/19/13					•		
40		*	Fan Integration	3 days	Fri 3/15/13	Sun 3/17/13					<b>I</b>		
41		*	Air Filter Integration	2 days	Fri 3/15/13	Sat 3/16/13					I		
42		*	<b>Printed Circuit Board</b>	15 days	Sat 3/23/13	Sat 4/6/13					_		
43		A .	PCB Layout	9 days	Sat 3/23/13	Sun 3/31/13							
44		AP	PCB Acquisition	3 days	Mon 4/1/13	Wed 4/3/13					:	I	
45		*	PCB Integration	3 days	Thu 4/4/13	Sat 4/6/13						1	
46		*	Web Interface	30 days	Sun 4/7/13	Mon 5/6/13							
47		*	Web Control Design	5 days	Sun 4/7/13	Thu 4/11/13						I	
48		*	Website Construction	16 days	Fri 4/12/13	Sat 4/27/13							
49		*	Website Integration	9 days	Sat 4/27/13	Sun 5/5/13							
50		*	Physical Prototype Done	0 days	Sun 3/17/13	Sun 3/17/13					<b>♦</b>	3/17	
51		*	Rasperry Pi Integration	12.13 days	Mon 3/25/13	Fri 4/5/13							
52		*	Web Cam Design	4 days	Sun 4/7/13	Wed 4/10/13							
53		AP	Web Cam Integration	2 days	Sat 4/13/13	Sun 4/14/13	52						
54		A.	Freeze Physical Design	0 days	Sat 3/30/13	Sat 3/30/13					•	3/30	
55		*	Freeze Software Design	0 days	Sun 4/21/13	Sun 4/21/13						4/23	ı
56		A.	Integration and Testing	21 days	Thu 5/16/13	Wed 6/5/13							5
57		=		·									
58		<b>*</b> 2											

