

Customer and Product Information

CQC Number	50144429	Order Date	12/19/2013	What was the Problem	Original Order Number50134198CQC CommentsThe unit was shipped in a metal enclosure but the enclosure should have been fiberglass.Serial Numbers:50134198-01	
Order Type	RPL	Symptom Code	002			
Customer RM		Symptom Description	Assy incorrect or incomplete			
Customer PO	4501151618	Responsible Dept	AED			
Customer Nam	ABB INC.	Unit Price	\$0.00			
Sold To	51	Planning Family	509	Contact Name	Randy Joyce	
Ship To	51	Internal Rep	Mathers, Chris	Contact Email		
Model Number	ITM509-00228856			Contact Phone	434-575-2112	
Order Total	1	Order Taken By:	BGROSS	Received Qty	1	PQR Status: Closed
Cell	927C	PQR Assigned To:	Applications Engineering	Material Received	1/7/2014	PQR Closed Date 1/10/2014
Line Number	1.1	Critical Class:	High	Received By	CTORRES	Customer Pain APPL
☒ Report???				Report Sent Date:	1/16/2014	
☐ If checked, THIS record will NOT appear on Specific Customer Report				Report By:	Tim Engelbrecht	

Make Individual Records



Unit # (of Total #) 1 of 1

Enter # of Units for this Record 1

MDC 11/15/2013

Serial Number(s) 50134198-01

Internal Observations issue credit; DRB 1/9/14

Observations for Customer Unit returned in new condition in the original packaging. The end user wanted a unit in a fiberglass enclosure rather than a steel enclosure. A steel enclosure was shipped to the end user inadvertently. Issue credit; DRB 1/9/14

Why #1 Wrong enclosure was used in the construction of this unit

Product Analysis

Analyzed By Don Beers

Oracle Disposition Date 1/9/2014

SEE CAUTION BELOW

Reason Cannot Receive:

Status in Oracle CLOSED

Email Quality

Select Next CQC

Print Analysis Report

Return to Main Menu

Preview Report of Findings

NOTE: Green highlighted fields contain data directly from Oracle RMA.

Why #2 conflicting information was provided to the manufacturing cell, some paperwork called for a steel enclosure, some called for a fiberglass enclosure.

Why #3 Conflicting information was generated incorrectly between the bill of materials, the configuration sheet and the grid traveler (Oracle CZ attributes)

Why #4 Attribute programming error in Oracle

Why #5 n/a

Root Cause Occurrence Attribute programming error in Oracle

Root Cause Non-Detection All orders for ABB are to be reviewed for discrepancies by the application engineers prior to releasing them to the floor for production

Immediate Countermeasure issue credit

Immediate Countermeasure Responsible

Due Date

Permanent Countermeasure The attributes in the Oracle business system have been updated and corrected so as to no longer generate conflicting paperwork

Permanent Countermeasure Responsible

Due Date

Non-Detection Countermeasure n/a

Non-Detection Countermeasure Responsible

Due Date

Method for Confirming Countermeasures

Defect Category AED - REQUIREMENTS NOT RELAYED

NOTE: Yellow highlighted fields MUST be completed as they will appear on the final report to the customer.

CAUTION: Analysis Completed Date should be entered ONLY when entire analysis is complete (root cause and countermeasures have been entered). EXCEPTION: Enter date if review for re-assignment is needed.

If analysis review finds incomplete or unacceptable data, this field MUST be re-entered in order to re-submit for review.



Analysis Completed Date

1/9/2014

Report Not Required ☐

Check box if FAB responsibility ☐

Check box if Supplier responsibility ☐

Inventory Adjustments (if any)

