

Customer and Product Information

CQC Number	50140790	Order Date	11/12/2013	What was the Problem	Original Order Number50137408CQC CommentsWrong connector entered by AE PG. Customer needs an 8-pin military style connector and received a 6-pin ANSI style connector.
Order Type	CRD	Symptom Code	124		
Customer RM		Symptom Description	Configured /ordered wrong		
Customer PO	735	Responsible Dept	AED		
Customer Nam	Northern Water	Unit Price	\$143.49		
Sold To	204470	Planning Family	CON	Contact Name	Dirk Banks
Ship To	204470	Internal Rep	Borer, Gregg	Contact Email	dbanks@northernwater.org
Model Number	CON-606-5			Contact Phone	970-622-2292
Order Total	4	Order Taken By:	MFRANCIS		
Cell	925A	PQR Assigned To:	Peter Goebel	Received Qty	4 PQR Status: Pending CM
Line Number	1.1	Critical Class:		Material Received	11/20/2013 PQR Closed Date
		☒ Report???		Received By	CTORRES Customer Pain APPL
		☐ If checked, THIS record will NOT appear on Specific Customer Report		Report Sent Date:	
				Report By:	

Make Individual Records



Unit # (of Total #) 1 of 4

Enter # of Units for this Record

MDC

Serial Number(s)

Internal Observations

Observations for Customer

Why #1

Product Analysis

Analyzed By Peter Goebel

Oracle Disposition Date 11/20/2013

SEE CAUTION BELOW

Reason Cannot Receive:

Status in Oracle

CLOSED

Email Quality

Select Next CQC

Print Analysis Report

Return to Main Menu

Preview Report of Findings

NOTE: Green highlighted fields contain data directly from Oracle RMA.

Why #2	AE incorrectly read interpreted the wiring diagram versus the connector callout.	
Why #3	Bill of materials was not referenced to determine connector insulator type.	
Why #4	AE read only one of the two wiring references on drawings.	
Why #5		
Root Cause Occurrence	AE read only one of the two wiring references on drawings.	
Root Cause Non-Detection	n/a	
Immediate Countermeasure	Check bill of materials for models that show multiple notes and diagrams for connectors on the drawings.	
Immediate Countermeasure Responsible		Due Date
Permanent Countermeasure	Document various wiring diagrams and notation styles on our product indices for connector assemblies. Release to the Application Engineering group by year end 2013. Continuously update chart as irregular or potentially confusing wiring diagrams surface.	
Permanent Countermeasure Responsible	Peter Goebel	Due Date 12/31/2013
Non-Detection Countermeasure	n/a	
Non-Detection Countermeasure Responsible		Due Date
Method for Confirming Countermeasures		
Defect Category	AED - ORDERED WRONG UNIT	

NOTE: Yellow highlighted fields MUST be completed as they will appear on the final report to the customer.

CAUTION: Analysis Completed Date should be entered ONLY when entire analysis is complete (root cause and countermeasures have been entered). EXCEPTION: Enter date if review for re-assignment is needed.

If analysis review finds incomplete or unacceptable data, this field MUST be re-entered in order to re-submit for review.



Analysis Completed Date 12/5/2013

Report Not Required ☐

Check box if FAB responsibility ☐

Check box if Supplier responsibility ☐

Inventory Adjustments (if any)

