



# CAD and 3D Printing Workshop 2024




Part 1: Base




## Step 1:




Step 2:




## Step 3:




#### Step 4:




## Step 5:



#### Step 6:




## Step 7:




## 0\_\_\_\_


## Step 8:




## Step 9:




#### **Step 10:**




## **Step 11:**




## **Step 12:**




## **Step 13:**




#### **Step 14:**




## **Step 15:**




#### **Step 16:**




## **Step 17:**




#### **Step 18:**




## **Step 19:**




#### **Step 20:**




## **Step 21:**



#### **Step 22:**




## **Step 23:**




## Part 2: Gear




## Step 1:




#### Step 2:




## Step 3:



Part 3: Cap




## Step 1:







## Step 2:



## Step 3:




#### Step 4:




## **Assembly**




## Step 1:




#### Step 2:




#### **Step 2.5:**




#### Step 3:



## **Step 3.5:**



#### Step 4:



#### **Step 4.5:**

