

# V213 Hood destructive test report For Glue 170419

北京奔驰

Audit Date: 2017-04-18

Conduct Department: QM/PA

Product Description: V213 SOP - 2#

Arrival date: 2017-4-11


Product ID:7040821033



Total	ОК	Prio1/2/3 NOK	Qualification rate	Remarks
149	146	3	97.9%	

# V213 Hood destructive test report For Glue 170419

北京奔驰




Glue NO. 88501224 (K) One-sided bond total: 80 mm Prio2.

Glue NO. 88501223 (K) One-sided bond & Spring back effect total: 65 mm Prio2.

# V213 Hood destructive test report For Glue 170419

北京奔驰



Glue NO. 88501225 (K) Spring back effect total: 15 mm. Prio3



# V213 Left Front door destructive test report

北京奔驰

### For Glue 170419


Audit Date: 2017-4-17

Conduct Department: QM/PA

Product Description: V213 SOP - #

Arrival date: 2017-4-11

Product ID:



Total	ОК	Prio1/2/3 NOK	Qualification rate	Remarks
19	19	0	100%	



# W213 Right Front door destructive test report Mercedes-Benz

### For Glue 170419

Audit Date: 2017-4-17

Conduct Department: QM/PA

Product Description: V213 SOP - 2#

Arrival date: 2017-4-11

Product ID:7041013474



Total	ОК	Prio1/2/3 NOK	Qualification rate	Remarks
19	19	0	100%	



# V213 Left Rear door destructive test report For Glue 170419

北京奔驰

Audit Date: 2017-04-17

Conduct Department: QM/PA

Product Description: V213 SOP - 2#

Arrival date: 2017-4-11

Product ID: 7040902271



Total	ОК	Prio1/2/3 NOK	Qualification rate	Remarks
15	15	0	100%	



# V213 Right Rear door destructive test report

#### 北京奔驰

### For Glue 170419

Audit Date: 2017-04-17

Conduct Department: QM/PA

Product Description: V213 SOP - 2#


Arrival date: 2017-4-11

Product ID:7040903584



Total	OK	Prio1/2/3 NOK	Qualification rate	Remarks
15	14	1	93.3%	

# V213 Right Rear door destructive test report Mercedes-Benz For Glue 170419



Glue No. 73032580 (F) Adhesive bead in wrong position total: 490 mm



# V213 Left Fender destructive test report For Glue 170419

北京奔驰


Audit Date: 2017-04-18

Conduct Department: QM/PA

Product Description: V213 SOP - 2#

Arrival date: 2017-4-11

Product ID:7040823582



Total	ОК	Prio1/2/3 NOK	Qualification rate	Remarks
15	15	0	100%	



# V213 Right Fender Destructive Test Report for Glue 170419

北京奔驰


Audit Date: 2017-04-18

Conduct Department: QM/PA

Product Description: V213 SOP - 2#

Arrival date: 2017-4-11

Product ID:7040909163



Total	ОК	Prio1/2/3 NOK	Qualification rate	Remarks
15	14	1	93.3%	

# V213 Right Fender Destructive Test Report for Glue 170419

北京奔驰



Glue NO. 88501546 (U )Gap between the parts too big total : 80 mm. Prio2



# V213 Trunk Lid destructive test report For Glue 170419

北京奔驰


Audit Date: 2017-04-18

Conduct Department: QM/PA

Product Description: V213 SOP - 2#

Arrival date: 2017-4-11


Product ID:7041010231



Total	ОК	Prio1/2/3 NOK	Qualification rate	Remarks
27	26	1	96.3%	

# V213 Trunk Lid destructive test report For Glue 170419

北京奔驰



Glue NO. 75000091 (U )Gap between the parts

too big total : 60 mm. Prio3