

Property: 3919 Highway 62 412

Hardy, AR 72542-9100

Claim Number: Type of Loss: Hail

Date of Loss: 3/30/2025 12:00 AM Date Received:

Date Inspected: Date Entered: 7/13/2025 7:51 AM

Price List: ARBA8X\_JUL25

Restoration/Service/Remodel

Estimate: 3919\_HIGHWAY622




### 3919\_HIGHWAY622

#### **General Conditions**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
R&R Tarp - all-purpose poly - per sq ft (labor and material)	1,690.00 SF	0.09	0.85	51.38	328.00	1,967.98
To protect the landscape/typography fro	om roofing debris*					
2. Temporary toilet - Minimum rental charge	1.00 EA	0.00	160.00	0.00	32.00	192.00
3. Temporary hand washing station - Minimum rental charge	1.00 EA	0.00	201.00	0.00	40.20	241.20
4. On-Site Evaluation and/or Supervisor/Admin - per hour	20.00 HR	0.00	59.15	134.87	236.60	1,554.47
5. Taxes, insurance, permits & fees (Bid Item)	1.00 EA	0.00	600.00	0.00	0.00	600.00
6. Fall protection harness and lanyard (per day)	32.00 DA	0.00	8.00	0.00	51.20	307.20
7. Temporary fencing - 1-4 months (per month)	160.00 LF	0.00	1.85	0.00	59.20	355.20
Totals: General Conditions				186.25	747.20	5,218.05

#### **Main Level**



#### Roof1

7,494.60 Surface Area 338.00 Total Perimeter Length 107.52 Total Hip Length 74.95 Number of Squares53.00 Total Ridge Length

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
8. Tear off, haul and dispose of comp. shingles - 3 tab	74.95 SQ	65.71	0.00	0.00	985.00	5,909.96
9. 3 tab - 25 yr comp. shingle roofing - w/out felt	86.33 SQ	0.00	269.22	1,007.54	4,849.86	29,099.16
86.33 SQ of shingles were required for	installation and cu	tting waste not inc	luding asphalt start	ter or ridge cap.		
10. Re-nailing of roof sheathing - complete re-nail	7,494.60 SF	0.00	0.18	7.12	271.22	1,627.37
11. Roofing felt - 15 lb.	74.95 SQ	0.00	40.45	64.72	619.28	3,715.73

Underlayment application: For roof slopes of four units vertical in 12 units horizontal (4:12) or greater, underlayment shall be one layer applied in the following manner: underlayment shall be applied shingle fashion, parallel to and starting from the eave and lapped 2 inches, Distortions in the underlayment shall not interfere with the ability of the shingles to seal. End laps shall be 4 inches and shall be offset by 6 feet. (Reference: International Residential Code R905.2.7)



#### **CONTINUED - Roof1**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
12. R&R Drip edge	418.00 LF	0.40	3.13	46.06	304.32	1,825.92
<b>R905. 2.8. 5 Drip Edge</b> Drip edge shall be provided at eaves an inches.	nd rake edges of shi	ngle roofs. Adjacen	t segments of the drip	edge shall be ove	rlapped no less ti	han two
13. Seal (1 coat) & paint (1 coat) trim	418.00 LF	0.00	2.02	5.96	170.08	1,020.40
To paint demarcation from drip edge re	emoval					
14. R&R Drip edge/gutter apron	338.00 LF	0.36	2.61	45.92	209.96	1,259.74
15. Ice & water barrier	1,014.00 SF	0.00	1.95	52.02	405.86	2,435.18
Per manufacture specifications with ov Reinstallation of Materials: Aggregate		s shall not be reinst	alled. ( <b>Reference: In</b>	ternational Resid	ential Code R907	7.6)
16. Asphalt starter - universal starter course	338.00 LF	0.00	2.28	17.98	157.72	946.34
17. R&R Hip / Ridge cap - Standard profile - composition shingles	160.52 LF	3.38	6.69	46.66	332.64	1,995.74
18. Bid Item	1.00 EA	0.00	7,100.00	0.00	0.00	7,100.00
IA photos show tarping on the room: G	C has sent in invoic	e				
19. Emergency Temporary Roof Repair	1.00 EA	0.00	10,335.00	0.00	0.00	10,335.00
4400sqft @ 2.30/sqft						
20. BID ITEM	1.00 EA	0.00	1,315.00	0.00	0.00	1,315.00
Inspection Fee Emergency Temporary Roof Repair Mi Roofer Labor- Minimum Service Call	inimum					

### ACCESSORIES

Totals: Roof1

Meeting with Adjuster- 5/30/2025

Reinstallation of Materials: Any existing flashings, edgings, outlets, vents or similar devices that are part of the assembly shall be replaced when rusted, damaged or deteriorated. (Reference: International Residential Code R907.5)

, ,			,			
21. R&R Roof vent - turbine type	3.00 EA	10.97	166.13	29.36	112.14	672.80
22. Prime & paint roof vent	3.00 EA	0.00	47.50	2.27	28.96	173.73
To restore to pre-storm condition						
23. R&R Flashing - pipe jack	5.00 EA	8.60	58.30	8.95	68.70	412.15
<b>Reinstallation of Materials:</b> Any existing y rusted, damaged or deteriorated. ( <b>Referen</b>	0.0.			e part of the assen	nbly shall be repla	ced when
24. R&R Custom bent aluminum (PER LF)	37.00 LF	2.70	19.84	13.15	169.44	1,016.57

1,347.71

8,685.18

70,860.79

#### **Front Elevation**



#### **CONTINUED - Front Elevation**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
25. R&R Gutter - aluminum - up to 5"	90.00 LF	0.54	8.17	34.63	163.70	982.23
26. R&R Downspout - aluminum - up to 5"	27.00 LF	0.54	8.17	10.39	49.12	294.68
27. Prime & paint gutter / downspout	119.00 LF	0.00	1.83	2.94	44.14	264.85
28. R&R Attic vent - gable end - vinyl - Large	1.00 EA	8.99	176.26	12.29	39.52	237.06
29. Remove Siding - board & batten - cedar	160.00 SF	0.47	0.00	0.00	15.04	90.24
SIDING REMOVED IN ORDER TO RTE	PLACE GABLE V	ENT				
30. Siding - board & batten - cedar	160.00 SF	0.00	9.70	108.38	332.08	1,992.46
31. Seal & paint wood siding	160.00 SF	0.00	2.07	8.21	67.88	407.29
Totals: Front Elevation				176.84	711.48	4,268.81

### **Rear Elevation**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
32. R&R Gutter - aluminum - up to 5"	90.00 LF	0.54	8.17	34.63	163.70	982.23
33. R&R Downspout - aluminum - up to 5"	27.00 LF	0.54	8.17	10.39	49.12	294.68
34. Prime & paint gutter / downspout	119.00 LF	0.00	1.83	2.94	44.14	264.85
35. R&R Overhead door & hardware - 16' x 7'	1.00 EA	89.97	1,704.66	136.65	386.28	2,317.56
36. Paint overhead door - 2 coats (per side)	1.00 EA	0.00	136.87	4.78	28.34	169.99
37. Scrape the surface area & prep for paint	540.00 SF	0.00	0.71	0.51	76.78	460.69
38. Exterior - paint two coats	540.00 SF	0.00	1.32	20.52	146.66	879.98
Totals: Rear Elevation				210.42	895.02	5,369.98

### **Right Elevation**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
39. R&R Gutter - aluminum - up to 5"	70.00 LF	0.54	8.17	26.93	127.32	763.95
40. R&R Downspout - aluminum - up to 5"	27.00 LF	0.54	8.17	10.39	49.12	294.68
41. Prime & paint gutter / downspout	97.00 LF	0.00	1.83	2.40	35.98	215.89
42. R&R Vinyl window - casement, 9-13 sf	1.00 EA	24.38	490.02	39.70	110.82	664.92
919_HIGHWAY622					8/24/2025	Page: 4



### **CONTINUED - Right Elevation**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
43. Scrape the surface area & prep for paint	420.00 SF	0.00	0.71	0.40	59.72	358.32
44. Exterior - paint two coats	420.00 SF	0.00	1.32	15.96	114.08	684.44
Totals: Right Elevation				95.78	497.04	2,982.20

#### **Left Elevation**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
45. R&R Gutter - aluminum - up to 5"	70.00 LF	0.54	8.17	26.93	127.32	763.95
46. R&R Downspout - aluminum - up to 5"	27.00 LF	0.54	8.17	10.39	49.12	294.68
47. Prime & paint gutter / downspout	97.00 LF	0.00	1.83	2.40	35.98	215.89
48. R&R Vinyl window - casement, 9-13 sf	2.00 EA	24.38	490.02	79.40	221.64	1,329.84
49. R&R AC unit - throughwall/window - 5,000 BTU	2.00 EA	33.95	706.84	98.69	316.06	1,896.33
50. Scrape the surface area & prep for paint	420.00 SF	0.00	0.71	0.40	59.72	358.32
51. Exterior - paint two coats	420.00 SF	0.00	1.32	15.96	114.08	684.44
Totals: Left Elevation				234.17	923.92	5,543.45

#### **Debris Removal**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
52. Dumpster load - Approx. 40 yards, 7-8 tons of debris	2.00 EA	1,000.00	0.00	228.00	400.00	2,628.00
Totals: Debris Removal				228.00	400.00	2,628.00
Total: Main Level				2,292.92	12,112.64	91,653.23
Line Item Totals: 3919_HIGHWAY622				2,479.17	12,859.84	96,871.28



### **Grand Total Areas:**

SF Walls	0.00	SF Ceiling	0.00	SF Walls and Ceiling
SF Floor	0.00	SY Flooring	0.00	LF Floor Perimeter
SF Long Wall	0.00	SF Short Wall	0.00	LF Ceil. Perimeter
Floor Area	0.00	Total Area	0.00	Interior Wall Area
Exterior Wall Area	0.00	Exterior Perimeter of		
		Walls		
Sauface Aug	74.05	Number of Course	220.00	Total Davinsatan I an oth
Surface Area	74.95	Number of Squares	338.00	Total Perimeter Length
Total Ridge Length 1	07.52	Total Hip Length		
	SF Floor SF Long Wall Floor Area Exterior Wall Area Surface Area	SF Floor 0.00 SF Long Wall 0.00 Floor Area 0.00 Exterior Wall Area 0.00 Surface Area 74.95	SF Floor SF Long Wall O.00 SY Flooring O.00 SF Short Wall  Floor Area O.00 Total Area Exterior Wall Area O.00 Exterior Perimeter of Walls  Surface Area 74.95 Number of Squares	SF Floor SF Long Wall O.00 SF Short Wall O.00 Floor Area O.00 Exterior Wall Area O.00 Exterior Perimeter of Walls  Surface Area 74.95 Number of Squares 338.00

Coverage	Item Total	%	ACV Total	%
Dwelling	76,566.81	79.04%	76,566.81	79.04%
Other Structures	0.00	0.00%	0.00	0.00%
Contents	20,304.47	20.96%	20,304.47	20.96%
Total	96,871.28	100.00%	96,871.28	100.00%



# **Summary for Dwelling**

Line Item Total Material Sales Tax	61,599.27 2,116.30
Subtotal	63,715.57
Overhead	6,311.62
Profit	6,311.62
Service Sales Tax	228.00
Replacement Cost Value Net Claim	\$76,566.81 \$76,566.81
100 Ciami	——————————————————————————————————————



# **Summary for Contents**

Line Item Total	19,933.00
Overhead	118.30
Profit	118.30
Service Sales Tax	134.87
Replacement Cost Value	\$20,304.47
Net Claim	\$20,304.47



# Recap of Taxes, Overhead and Profit

Overhead (10%)	<b>Profit</b> (10%)	Material Sales Tax (9.5%)	Cleaning Matl Tax (9.5%)	Service Sales Tax (9.5%)	Manuf. Home Tax (6.5%)	Storage Rental Tax (9.5%)	State Food Tax (1.5%)	Local Food Tax (3%)
Line Items								
6,429.92	6,429.92	2,116.30	0.00	362.87	0.00	0.00	0.00	0.00
Total								
6,429.92	6,429.92	2,116.30	0.00	362.87	0.00	0.00	0.00	0.00



# **Recap by Room**

Estimate: 3919_HIGHWAY622		4.204.60	<b>7.</b> 040/
General Conditions		4,284.60	5.26%
Coverage: Dwelling	72.39% =	3,101.60	
Coverage: Contents	27.61% =	1,183.00	
Area: Main Level			
Roof1		60,827.90	74.61%
Coverage: Dwelling	69.18% =	42,077.90	
Coverage: Contents	30.82% =	18,750.00	
Front Elevation		3,380.49	4.15%
Coverage: Dwelling	100.00% =	3,380.49	
Rear Elevation		4,264.54	5.23%
Coverage: Dwelling	100.00% =	4,264.54	
Right Elevation		2,389.38	2.93%
Coverage: Dwelling	100.00% =	2,389.38	
Left Elevation		4,385.36	5.38%
Coverage: Dwelling	100.00% =	4,385.36	
Debris Removal		2,000.00	2.45%
Coverage: Dwelling	100.00% =	2,000.00	
Area Subtotal: Main Level		77,247.67	94.74%
Coverage: Dwelling	75.73% =	58,497.67	
Coverage: Contents	24.27% =	18,750.00	
Subtotal of Areas		81,532.27	100.00%
Coverage: Dwelling	75.55% =	61,599.27	
Coverage: Contents	24.45% =	19,933.00	
Total		81,532,27	100.00%



# **Recap by Category**

O&P Items			Total	%
CONT: GARMENT & SOFT GOODS CLN			1,183.00	1.22%
Coverage: Contents	@	100.00% =	1,183.00	
GENERAL DEMOLITION			8,630.63	8.91%
Coverage: Dwelling	@	100.00% =	8,630.63	
DOORS			1,704.66	1.76%
Coverage: Dwelling	@	100.00% =	1,704.66	
HEAT, VENT & AIR CONDITIONING			1,413.68	1.46%
Coverage: Dwelling	@	100.00% =	1,413.68	
PAINTING			5,046.89	5.21%
Coverage: Dwelling	@	100.00% =	5,046.89	
ROOFING			34,424.75	35.54%
Coverage: Dwelling	@	100.00% =	34,424.75	
SCAFFOLDING			256.00	0.26%
Coverage: Dwelling	@	100.00% =	256.00	
SIDING			2,462.34	2.54%
Coverage: Dwelling	@	100.00% =	2,462.34	
SOFFIT, FASCIA, & GUTTER			3,496.76	3.61%
Coverage: Dwelling	@	100.00% =	3,496.76	
TEMPORARY REPAIRS			2,093.50	2.16%
Coverage: Dwelling	@	100.00% =	2,093.50	
WINDOWS - VINYL			1,470.06	1.52%
Coverage: Dwelling	@	100.00% =	1,470.06	
O&P Items Subtotal			62,182.27	64.19%
Non-O&P Items			Total	%
PERMITS AND FEES			600.00	0.62%
Coverage: Dwelling	@	100.00% =	600.00	
USER DEFINED ITEMS			18,750.00	19.36%
Coverage: Contents	@	100.00% =	18,750.00	
Non-O&P Items Subtotal			19,350.00	19.97%
O&P Items Subtotal			62,182.27	64.19%
Material Sales Tax			2,116.30	2.18%
Coverage: Dwelling	@	100.00% =	2,116.30	
Overhead			6,429.92	6.64%
Coverage: Dwelling	@	98.16% =	6,311.62	
Coverage: Contents	@	1.84% =	118.30	C C 40 /
Profit  Conseque Describing	G	00.170/	6,429.92	6.64%
Coverage: Dwelling	@	98.16% =	6,311.62	
Coverage: Contents Service Sales Tax	@	1.84% =	118.30 <b>362.87</b>	0.37%
Coverage: Dwelling	@	62.83% =	228.00	U.3770
919_HIGHWAY622			8/24/2025	Page:



 Coverage: Contents
 @
 37.17% =
 134.87

 Total
 96,871.28
 100.00%



Main Level