Reference Table of Engraving Power & Speed

Laser Master 2 - With LU7W

| | | | IOLUI Z WI | |
|--|----------|-------------|--------------------------|--|
| LU7W | Engrave | Recomended | Recomended | |
| | or Cut | Power Range | 0 0 1 | Remark |
| Materials | or cut | S0-S1,000 | mm/Min | |
| Plywood | Engrave | S1,000 | 2,000mm/min | It need to be adjusted based on different woods, different colors. |
| Paperboard (Cardboard Box) | Engrave | S1,000 | 3,000mm/min | It need to be adjusted based on different thickness paperboards, different colors. |
| | Cut | S1,000 | 200mm/min | |
| | | | Run 2 round | |
| 250g Kraft Paper | Engrave | S1,000 | 3,000mm/min | It need to be adjusted based on different colors. |
| | Cut | S1,000 | 200mm/min | |
| | | | Run 1 round | |
| 5MM KT Board | Cut | S1,000 | 600mm/min | It need to be adjusted based on different colors. |
| (Dark color) | | | Run 1 round | There will be black edges after cutting |
| Non-woven fabrics (0.1~0.5mm, Dark color) | Cut | S1,000 | 500mm/min Run 1 round | Cannot cut Non-woven in white color |
| | | | | It need to be adjusted based on different colors. |
| | | | | There will be black edges after cutting |
| Cotton Cloth (Dark color) | Cut | S1,000 | 500mm/min Run 1 round | Some cotton blended fabrics may be melt. |
| | | | | It need to be adjusted based on different colors. |
| (Dark color) | | | Kuli i louliu | There will be black edges after cutting |
| 0.7MM Leather | Engrave | S1,000 | 3,000mm/min | It need to be adjusted based on different leathers, different colors. |
| | Cut | S1,000 | 100mm/min | |
| | | | Run 1 round | |
| Some Plastic Sheet | | | | Some plastic sheets may be melt. |
| (Dark Color) | Engrave | S1,000 | 2,000mm/min | It need to be adjusted based on different colors, |
| (Dark Color) | | | | different colors. |
| Solid wood | Engrave | S1,000 | 2,000mm/min | It need to be adjusted based on different woods, |
| Sond Wood | Biigiuve | 51,000 | 2,000111111111111 | different colors. |
| Acrylic | Engrave | S1,000 | 2,000mm/min | Cannot engrave transparent Acrylic directly, |
| Act yiic | Liigiave | 51,000 | 2,0001111111111111 | need to paste Kraft paper film on the surface. |
| | | | | Engraved on powder coating. |
| Powder Coated Metal | Engrave | S1,000 | 2,000mm/min | It need to be adjusted based on different finishings |
| | | | | and colors. |
| Paint Sprayed Metal | Engrave | S1,000 | 2,000mm/min | Engraved on Paint layer. |
| | | | | It need to be adjusted based on different finishings |
| | | | | and colors. |
| Plated Metal | Engrave | S1,000 | 2,000mm/min | It's the surface color turned to be other color. |
| | | | | Need to use Marker to balck the finishing first. |
| | | | | It need to be adjusted based on different finishings |
| | | | | and colors. |
| | | | | It's the surface color turned to be other color. |
| Anodised Aluminium | Engrave | S1,000 | 2,000mm/min | It need to be adjusted based on different finishings |
| | | | | and colors. |

The results would be different in even same material with different finishing or different colors, **So you need to adjust.** It couldn't engrave or cut directly: Glossy metal plate, Transparent materials, Reflecting materials, Some materials in white color or pervious to light, etc. Then, you need to use the marker pen to black it to engrave.

ATTENTION:

- 1. Do NOT operate laser without eye protection (Laser goggles).
- 2. Please set up laser engraver in the fireproofing area, with good ventilation.
- 3. Please keep minors (especially kids younger than 14 yours old) away from this laser engraver.
- 4. Please take care the laser engraver when it is working.
- 5. Please do not touch the laser beam with your hands or any other objects.