Reference Table of Engraving Power & Speed of Laser Master & Laser Master 1 & Laser Master 2 - With LU20W

LU20W		Dagamandad	Recomended	doi mudidi 2 Milli 1020M
LOZOW	Engrave		Engraving Speed	Remark
M	or Cut		0 1	Kemai k
Materials	E	S0-S1,000	mm/Min	
1 CMM DI	Engrave	S800	3,000mm/min	It need to be adjusted based on different woods,
1.6MM Plywood	Cut	S1,000	200mm/min	different colors.
	Г	g000	Run 1 round	
3MM Plywood	Engrave	S800	3,000mm/min	It need to be adjusted based on different woods,
	Cut	S1,000	100mm/min	different colors.
		7	Run 2 rounds	
Paperboard	Engrave	S200	3,000mm/min	It need to be adjusted based on different thickness
(Cardboard Box)	Cut	S1,000	1,000mm/min	paperboards, different colors.
,		,	Run 3 rounds	1 1
A#0 XX 0: D	Engrave	S200	3,000mm/min	
250g Kraft Paper	Cut	S1,000	1,000mm/min	It need to be adjusted based on different colors.
		,	Run 1 round	
5MM KT Board	Cut	S1,000	2,000mm/min	It need to be adjusted based on different colors.
(Dark color)		51,000	Run 1 round	There will be black edges after cutting
Non-woven fabrics	Cut	S1,000	1,600mm/min	It need to be adjusted based on different colors.
(0.1~0.5mm, Dark color)	Cui	31,000	Run 1 round	There will be black edges after cutting
Cattara Clath			1.200/	Some cotton blended fabrics may be melt.
Cotton Cloth	Cut	S1,000	1,200mm/min	It need to be adjusted based on different colors.
(Dark color)			Run 1 round	There will be black edges after cutting
0.7MM Leather	Engrave	S400	3,000mm/min	
	Cut	\$1,000	500mm/min	It need to be adjusted based on different leathers,
			Run 1 round	different colors.
Some Plastic Sheet				Some plastic sheets may be melt.
	Engrave	S800	3,000mm/min	It need to be adjusted based on different
(Dark Color)				colors, different colors.
Solid wood	Engrave	S800	3,000mm/min	It need to be adjusted based on different woods,
Solid Wood	Liigiave	5000	3,00011111/111111	different colors.
Acrylic	Engrave	S800	3,000mm/min	Cannot engrave transparent Acrylic directly,
Tieryne		2000	2,0001111111111111	need to paste Kraft paper film on the surface.
Powder Coated Metal	-	G4 000	2000	Engraved on powder coating.
Paint Sprayed Metal	Engrave	S1,000	3,000mm/min	It need to be adjusted based on different finishings
				and colors.
Plated Metal	Engrave	S1,000	3,000mm/min	It's the surface color turned to be other color.
				Need to use Marker to balck the finishing first.
				It need to be adjusted based on different finishings
				and colors.
, , , , , , ,		G1 000	2 000 / :	It's the surface color turned to be other color.
Anodised Aluminium	Engrave	S1,000	3,000mm/min	It need to be adjusted based on different finishings
				and colors.
Cobblestone	Engrave	S1,000	100mm/min	The surface should be coated with acrylic dye heat
	<i>G</i>	,		transfer film.
Stainless Steel	Engrave	S1,000	100mm/min	The surface should be painted black by Marker Pen.
	0	, , , , , , ,		1

The results would be different in even same material with different finishing or different colors, **So you need to adjust.** It couldn't engrave or cut directly: Glossy metal plate, Transparent materials, Reflecting materials, Some materials in white color or pervious to light, etc. Then, you need to use the marker pen to black it to engrave.

ATTENTION:

- 1. Do NOT operate laser without eye protection (Laser goggles).
- 2. Please set up laser engraver in the fireproofing area, with good ventilation.
- 3. Please keep minors (especially kids younger than 14 yours old) away from this laser engraver.
- 4. Please take care the laser engraver when it is working.
- 5. Please do not touch the laser beam with your hands or any other objects.