





*Note:

Pre-Charge high side MUST be supplied through shutdown

circuit. Control will be through low side

Cascadia CM200DX

Inverter

Cascadia CM200DX Inverter

To ECU

Battery Segments

IMD

Temp

Monitor

BMS

To Shutdown Circuit

Fuse

Pre-Charge

Isolation

Relays

Tractive System
Active Light (TSAL)

Low Voltage SystemShutdown Wiring

Emrax 188HV Motor (Right Drive)

Emrax 188HV Motor

(Left Drive)



