


(a) Mode 1: Constant Symbol Power ($P_s = P_0$)**(b) Mode 2: Constant Transmission Energy Budget ($E_{tx} = E_0$)**