

Quality Control Manual

1. Inspection Standards

All products undergo inspection prior to shipment. Inspectors check for defects, packaging integrity, and correct labeling. A minimum pass rate of 80% is expected.

2. Defect Reporting

Defects found during inspections must be logged with severity and description. High severity defects require immediate action.

3. Continuous Improvement

Quality control teams review defect data monthly to identify trends and implement corrective actions.

4. Training and Certification

Inspectors complete annual certification and quarterly refresher courses. Training records are maintained.

5. Sampling Procedures

Random sampling is employed with at least 10% of all shipments inspected. Sampling rates increase with quality issues.

6. Equipment Calibration

All inspection equipment is calibrated biannually to ensure accuracy. Calibration logs are maintained.

7. Supplier Quality

Incoming materials from suppliers are evaluated quarterly. Supplier scorecards influence ordering decisions.