



Interferences

RPM Cable

Question:

The manual says to coil RPM cable many times, why AiM does not give this suggestion?

Answer:

In 2T engines the signal is strong enough: coiling many times the RPM cable on the sparkplug wire could generate issues, like these described in the FAQ concerning MyChron5 display.