



Channels

## Gas temperature

## **Question:**

Exhaust gas thermocouple (EGT) shows unexpected values.

## **Answer:**

Check that the sensor is correctly installed. If the problem persists replace the sensor. Newer sensor are more resistant and can be identified by their curve shape.