


## VOUT=1.27(1+R26/R31)



±êÌâ	Sensor Accessories Board		°æ3⁄4	V0	³₿ç	В	Ò⁵Âë 2 / 3
¹«Ë¾	Mileseey	×÷Õß	Sun JD		ʱ¼ã	2012-07-11	

