Service | Pre-delivery report | RO-58004

VIN: 2T3RFREV8FW123456

Vehicle: Toyota RAV4 demonstration vehicle

Visited: 2026-10-04

Related deal: DEAL-1014

Work: Fluid checks, tire inspection and battery load test

Finding: Battery below test threshold; replacement requested

Warranty reference: WC-2026-0204

Fictional sample only. Not a real transaction, policy or service record.