Service | Pre-delivery report | RO-58005

VIN: 3FA6P0H74HR123456

Vehicle: Ford Fusion demonstration vehicle

Visited: 2026-10-05

Related deal: DEAL-1015

Work: Fluid checks, tire inspection and battery load test

Finding: Battery below test threshold; replacement requested

Warranty reference: WC-2026-0205

Fictional sample only. Not a real transaction, policy or service record.