## Introduction to Uncertainties (prepared for physics 15 and 17)

**Average deviation**. When you have repeated the same measurement several times, common sense suggests that your "best" result is the average value of the numbers. We still need to know how "good" this average value is. One measure is called the average deviation. The average deviation or "RMS deviation" of a data set is the average value of the absolute value of the differences between the individual data numbers and the average of the data set. For example if the average is  $23.5 \, \text{cm/s}$ , and the average deviation is  $0.7 \, \text{cm/s}$ , then the number can be expressed as  $(23.5 \pm 0.7) \, \text{cm/sec}$ .

- **Rule 0. Numerical and fractional uncertainties.** The uncertainty in a quantity can be expressed in numerical or fractional forms. Thus in the above example,  $\pm 0.7$  cm/sec is a numerical uncertainty, but we could also express it as  $\pm 2.98\%$ , which is a fraction or %. (Remember, %'s are hundredths.)
- **Rule 1. Addition and subtraction**. If you are adding or subtracting two uncertain numbers, then the <u>numerical</u> uncertainty of the sum or difference is the sum of the <u>numerical</u> uncertainties of the two numbers. For example, if  $A = 3.4 \pm .5$  m and  $B = 6.3 \pm .2$  m, then  $A+B = 9.7 \pm .7$  m, and  $A-B = -2.9 \pm .7$  m. Notice that the numerical uncertainty is the same in these two cases, but the fractional uncertainty is very different.
- **Rule2. Multiplication and division**. If you are multiplying or dividing two uncertain numbers, then the <u>fractional</u> uncertainty of the product or quotient is the sum of the <u>fractional</u> uncertainties of the two numbers. For example, if  $A=3.4\pm.5$  m, and  $B=0.334\pm.006$  sec, the since  $A=3.4\pm14.7\%$  and  $B=0.334\pm1.80\%$ , then A/B=10.180 m/s  $\pm16.5\%$ , or  $A/B=(10.180\pm1.68)$  m/s. Also, AB=1.1356 m-sec  $\pm16.5\%$  or  $(1.1356\pm.187)$  m-sec. Notice that the fractional uncertainties are the same, but the numerical uncertainties are different (even different units).
- **Rule 3. Raising to a power**. If you are raising an uncertain number to a power n, (squaring it, or taking the square root, for example), then the <u>fractional</u> uncertainty in the resulting number has a <u>fractional</u> uncertainty n times the fractional uncertainty in the original number. Thus if you are calculating a number  $y = \frac{1}{2}gt^2$ , where  $t = 2.36 \pm .04$  sec, then the uncertainty in  $t^2$  is  $t^2$  is  $t^2$ .
- **Rule 4. Complicated expressions**. In cases other than the above, you can do a numerical calculation to find the numerical uncertainty. We could call this the "max/min" method. For example, if you are calculating  $F_x = F\cos\theta$ , where  $\theta = 34.6 \pm .2$ °, and  $F = 13.2 \pm .7$  N, then we do a two-step calculation:
  - Step 1: calculate the uncertainty in  $\cos\theta$  by comparing  $\cos(34.6)$  to  $\cos(34.6 + .2)$ . The uncertainty in  $\cos\theta$  is taken as the difference between these numbers. Thus  $\cos(34.8) \cos(34.4) = 0.00396$ , then  $\cos(34.6 \pm .2) = 0.8231 \pm .00396$ .
  - Step 2: Use rule 2 above to calculate the uncertainty in F cos $\theta$ . The result is F cos $\theta$  = 10.865 N  $\pm$  5.78% or (10.865  $\pm$  .628) N.
- **Rule 5. Significant figures**. Once you get to a <u>final</u> result (no more computations are to be made with the quantity), then we usually keep one significant figure in the value of the uncertainty, and round off the quantity itself accordingly. Thus the final result in the rule 4 example is  $10.9\pm.6$  N, and the final result in the examples of rule 2 are  $(10\pm2)$ m/sec and  $(1.1\pm.2)$  m-sec.

Note: These simple rules are not quite "correct", but they will serve pretty well in the first course in physics.

CCJ 1/8/98