Network Working Group RFC #305 NIC #9078 Ralph Alter BBN 23 February 1972

UNKNOWN HOST NUMBERS

In response to a recent minor flurry of confusion, it seems worth announcing publicly the fact that new IMPs are tested (almost always) on the ARPA Net here at BBN before delivery to the intended site. Accordingly, sites should not be surprised to receive RFCs or at least RSTs from IMPs or Hosts they thought didn't exist, or at least did not exist yet.

Occasionally, IMPs of some given configuration are tested in a mode where they announce their IMP number as different from what it will be when finally installed. A variety of reasons may create such a situation. The latest such occurrence is that a TIP, to be installed shortly at ETAC with IMP number 20 (replacing the 316 IMP now at ETAC which is number 20) was recently tested here with McClellan's IMP number (22). (It couldn't be tested with its own number since the 316 IMP currently at ETAC is using that number.) The result was RSTs from the TIP (Host 3) at IMP 22 - which is network address 150 (226 octal or 96 hex).

One site asked if their Host tables needed updating. The answer is _NO_. We fully expect IMPs tested under these circumstances to be ignored or CLS'd by some Hosts. We suggest that Host tables (where they are thought to be necessary) be modified only in response to official notification from BBN via either an RFC or an update to Appendix A of BBN Report #1822.

RA/jm

[This RFC was put into machine readable form for entry] [into the online RFC archives by BBN Corp. under the] [direction of Alex McKenzie. 12/96]

[Page 1]