

Service Report

Generated on 6/25/2025

Report Information		Service Details	
Company:	N/A	Service Number:	SWF-00414413
Contact:	Anonymous User	Device Serial:	MXX-2024-012345
Quote Number:	q111	Ticket Number:	2506190003
Invoice Number:	inv222	Started:	6/25/2025

Service Information

Initial Assessment	
Serial Number Received	Defect Description
MXX-2024-012345	defect description, test

Loaner Assignment	
Loaner Serial Number	Loaner Model
loaner sn	loaner bwiii eeg

Receiving & Cleaning

Date Received

Cleaning Date

7/1/2025

7/1/2025

Product ID Date

Inspection Comments

7/2/2025

arrived broken

Received Parts

Part Number	Description	Quantity	Serial Number
PV	amp	1	sn123
SI	headbpox	1	sn 456

Analysis & Diagnosis

Analysis Date

Finding Description

6/25/2025

found eas 3 broken

Description

amp (Serial: sn123), headbpox (Serial: sn 456)

Diagnostic Summary

LED not on

Replacement Parts

Part Number	Description	Quantity	Serial Number
rmboard	eas3	1	-
rm board2	eas2	1	-

Repair & Testing					
Description					
eas3 (Part #: rmboard), eas2 (Part #: rm board2)					
Repair Description					
board exchange					
Parts Used in Repair					
Part Number	Description	Quantity	Serial Number		
123	eas2	1	XXXX		
456	eas3	1	ууу		
Test Checklist	Test Checklist				
✓ PowerTest: Yes ✓ FunctionalTest: Yes ✓ CalibrationTest: Yes ✓ SafetyTest: Yes ✓ FinalTest: Yes					
Repair Approval Responsible Age	nt				
Mike Senior					
Mike Senior		N/A			
Service Responsible			Report Approval		
Service Responsible Report Approval					

Generated: 6/25/2025, 4:34:09 PM