

Service Report

Generated on 6/25/2025

Report Information		Service Details	
Company:	N/A	Service Number:	SWF-00414413
Contact:	Anonymous User	Device Serial:	MXX-2024-012345
Quote Number:	q111	Ticket Number:	2506190003
Invoice Number:	inv222	Started:	6/25/2025

Service Information

Initial Assessment	
Serial Number Received	Defect Description
MXX-2024-012345	defect description, test

Loaner Assignment	
Loaner Serial Number	Loaner Model
loaner sn	loaner bwiii eeg

Receiving & Cleaning

Date Received

Cleaning Date

7/1/2025

7/1/2025

Product ID Date

Inspection Comments

7/2/2025

arrived broken

Received Parts

Part Number	Description	Quantity	Serial Number
PV	amp	1	sn123
SI	headbpox	1	sn 456

Analysis & Diagnosis

Analysis Date

Finding Description

6/25/2025

found eas 3 broken

Description

amp (Serial: sn123), headbpox (Serial: sn 456)

Diagnostic Summary

LED not on

Replacement Parts

Part Number	Description	Quantity	Serial Number
rmboard	eas3	1	-
rm board2	eas2	1	-

Repair & Testing Description eas3 (Part #: rmboard), eas2 (Part #: rm board2) **Repair Description** board exchange Parts Used in Repair Description Quantity Serial Number Part Number 123 eas2 XXXX 456 eas3 1 ууу **Test Checklist** PowerTest: Yes FunctionalTest: Yes CalibrationTest: Yes SafetyTest: Yes FinalTest: Yes Repair Approval Responsible Agent Mike Senior Mike Senior **Mike Senior** Service Responsible Report Approval

Generated: 6/25/2025, 4:36:31 PM