

FOUNTAIN VALLEY FIRE DEPARTMENT 10200 Slater Ave., Fountain Valley CA 92708

Fire and Life Safety Inspection Notice 714-593-4436() 593-4491()593-4492()

	Zhah 1		
BUSINESS NAME: 605 WAG	INSPECTION DATE:	1000	
ADDRESS: 17 850 NEWHOPE	BUSINESS PHONE: 71 4 979	1376	
NOTICE ISSUED TO: LANNIE CITY: Fountain Valley, CA 92708			
RECIPIENT SIGNATURE OWNE	r □Manager □Employee □Other		
iolation/ Corrected			
COESS			
☐ Maintain FIRE LANE free of obstructions		CFC 503.4	
☐ Provide ADDRESS visible from street/contrasting from background		CFC 505.1	
Provide KNOX BOX for emergency access by Fire Department		CFC 506.1	
LANS AND PERMITS		CFC 105.6	
□ Obtain City BUSINESS LICENSE (593-4421) FIRE PERMIT for			
Secure PERMITS and submit PLANS toBUILDING DepartmentFIRE Department	icin ior.	CBC 105.1	
Repair exit DOOR/HARDWARE Location		CFC 1030.1	
Provide SIGN on front door (Minimum 1" letters) "This door to remain unlocked during l	ousiness hours"	CFC 1008.1.9	
☐ Provide or maintain EXIT SIGN Illuminated Location		CFC 1030.4	
Remove secondary LOCKS, LATCHES OR BOLTS from required exits Location		CFC 1008.1.9	
TRE PROTECTION SYSTEMS			
Provide FIRE EXTINGUISHER (S) 2A10BC 20 BC 40BC 1A10BC		CCR T-19	
SERVICE and TAG extinguisher(s) annually, **Note: If new extinguisher is purchased, post	eceipt on extinguisher.	CCR-T19	
MOUNT extinguisher(s) on bracket, maximum 5 feet from floor Location		CCR-T19	
Service KITCHEN HOOD SYSTEMS semi-annually		CCR-T19	
Clean FILTERS, DUCTS and HOODS above cooking surface		CFC 609.3.3 CCR-T19	
Obtain 5-YEAR CERTIFICATION on sprinkler/standpipe system			
 □ Obtain ANNUAL TEST of Automatic Fire Sprinkler System □ Maintain QUARTERLY MAINTENANCE RECORDS for sprinkler/standpipe system 			
☐ Maintain QUARTERLY MAINTENANCE RECORDS for sprinkler/standpipe system ☐ Replace damaged, painted, missing SPRINKLER HEADS/ FDC CAPS Location		CCR-T19 NFPA 13	
Provide SPARE sprinkler heads SPRINKLER WRENCH		NFPA 13	
Repair/replace FIRE WALL DRAFT STOPS RATED CEILING Location		CFC 703.1	
☐ Provide/ maintain operable SMOKE DETECTORS in each dwelling unit		CFC 907.2.10	
☐ Maintain, repair, inspect and/or test FIRE ALARM system annually		CCR T-19	
HECTRICAL			
☐ Discontinue use ofEXTENSION CORDS MULTI-PLUG ADAPTERS Location	on	CFC 605.5 CFC 605.6	
☐ Replace ELECTRICAL Cover socket blank wiring Location			
☐ Keep 30" CLEARANCE around ELECTRICAL PANEL Location			
☐ Identify and LABEL ELECTRICAL ROOMS and PANELS		CFC 605.3.1	
TORAGE ☐ Reduce storage to 24" below ceiling or 18" below sprinkler heads Location		CFC 315.3.1	
☐ Maintain COMBUSTIBLE STORAGE in an orderly manner Location		CFC 315.3	
Remove STORAGE or obstruction from EXITS AISLES STAIRWAYS Location	on	CFC 315.3.2	
Remove COMBUSTIBLE STORAGE from water heater, mechanical and/or electrical r		CFC 305.3.3	
IAZARDOUS MATERIALS SAFETY			
☐ Provide approved SAFETY CAN with lid for oily rags		CFC 2311.2.3	
☐ Secure all compressed gas CYLINDERS to prevent falling Location .		CFC 5303.5	
IAZARDOUS MATERIALS DISCLOSURE		School State Co.	
Failure to implement and/ or electronically submit a HMBP www.esubmit.ocgov.com		HSC 6.95	
☐ Failure to submit annual certification		HSC 6.95	
Chemical Inventory is incomplete and/ or requires updating	vection and/or Employee Training	HSC 6.95	
The Emergency Response Plan does not adequately address Notification, Mitigation, Evan	cuation, and of Employee Training	HSC 6.95	
☐ Site map is incomplete or insufficient ☐ Failure to report a change in business or chemical inventory within 30 days of the following	100% or more increase in	1150 0.55	
quantity of disclosed materialAddition of a previously undisclosed materialChan	ge of business name or owner	HSC 6.95	
Failure to report a release or threatened release		HSC 6.95	
ADDITIONAL REQUIREMENTS			
WE HAVE INSPECTED YOUR PREMISES FOR COMPLIANCE WITH THE CALIFORNIA FIRE C	ODE, FVMC AND OTHER RECOGNIZE		
TANDARDS HAVE ALL VIOLATIONS CORRECTED AND READY FOR REINSPECTION ON O	RAFTER 7/X//4	IF VIOLATIO	
RE NOT CORRECTED BY THIS DATE, THERE WILL BE A \$70.00 FEE FOR THE 3rd VISI	T. EACH ADDITIONAL VISIT WILL	BE BILLED	
DDITIONAL \$70.00 FEE UNTIL CORRECTIONS ARE COMPLETED.			

Inspection Log				
Initial Inspection	Reinspection	Final Notice Issued	Fee Issued	Referred to FPB
01 10	-			